

FIG. 1





FIG. 2






FIG. 4




FIG. 5

FIG. 5




FIG. 6




FIG. 7(a)

ALTERNATIVE CONNECTION ASSIGNMENT TABLE 51

TARGET VPI/VCI	COPY SOURCE VPI/VCI	COPY DESTINATION VPI/VCI	Alternative Route
0/32	50/100	51/100	0
:	:	:	:

51a
51b
51c
51d

FIG. 7(b)

51d

0	Alternative Route NOT UTILIZED
1	Alternative Route UTILIZED

FIG. 8

52

RECEIVING SIDE HEADER INVERSE
CONVERSION TABLE

53

I-ICID-A	VPI/VCI	Enable
100	0/32	1
101	0/32	0

FIG. 8

FIG. 9




FIG.10





FIG.11

PARAMETER	CONTENTS	NOTE
CV	CODING VIOLATION	ABOUT BIT ERROR, PRESENT OR NOT
ES	ERRORED SECOND	NUMBER OF DETECTED EVENTS OF CV, AIS AND SO ON
SES	SEVCRELY ERRORED SECOND	ERROR SUCH AS CV, AIS AND SO ON LARGER THAN ES
SAS	SEF/AIS SECOND	
AISS	AIS SECOND	
UASP	UNAVAILABLE SECOND	

FIG. 12

FIG.12



FILED 10030500

FIG.13




FIG.14




FIG.14

FIG. 15




FIG. 16




FIG. 17




FIG. 18




FIG. 20




FIG. 21




FIG. 22




FIG. 23




FIG. 24




FIG. 25

